



## Fish Ladder Monitoring Report for November 16th through November 22nd, 2020

For the week of November 16<sup>th</sup>, the ladder was observed on the 17<sup>th</sup> and the 20<sup>th</sup> for a minimum of one hour during each observation. Access was not available to the ladder side of the river, so observations took place along the intake side. River discharge on Nov. 17<sup>th</sup> was 875 cfs during the time of observation and reached 575 cfs during observation on Nov. 20<sup>th</sup>. Due to inaccessibility, a ladder discharge measurement or reading could not be taken, and ladder discharge was estimated at 65-70 cfs on the 17<sup>th</sup>, and 60-65 cfs on the 20<sup>th</sup>.

No fish were observed this week at the ladder or the surrounding spillway area. No obstructive woody debris accumulated within 100 m of the ladder, and the bedload present in the ladder is not adversely affecting flow or ladder function. Bedload accumulation will be removed in the next few weeks.



Ladder outflow on Nov. 17th



Ladder outflow on Nov. 20th